EAST Search History

Ref#	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	344	(417/500).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/03/24 08:17
S2	1	("4412519").PN.	USPAT	OR	OFF	2008/03/24 12:41
S3	1	("5181585").PN.	USPAT	OR	OFF	2008/03/24 12:44
S4	383	diesel with fuel with lubrication	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 13:43
S5	61	S4 with pump	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 13:43
S6	2	("6540486").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/03/24 15:13
\$7	12	("4223558" "4323097" "4941809" "5015157" "5020980" "5044889" "5102310" "5246354" "5279210" "5482448" "5863187" "6224347").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/24 15:14
S8	1	("6322336").PN.	USPAT	OR	OFF	2008/03/24 15:29

S9	21	"rack and pinion" with piston	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 15:46
S10	9882	"worm gear" and piston	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 15:58
S11	1016	"worm gear" with piston	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 15:59
S12	18	S11 and "stepping motor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 16:00
S13	344	(417/500).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/03/25 15:32
S14	14	S13 and step\$4 near2 motor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:32
S15	28707	gear near2 cam	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:48
S16	4563	S15 and piston	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:48

S17	1484	S16 and piston with reciproca\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:48
S18	139	S16 and piston with reciproca\$4 with (gear near2 cam)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/25 15:48
S19	344	(417/500).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/03/26 08:34
S20	0	S19 and "Hall sensor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/26 08:34
S21	4	S19 and "position sensor"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/26 08:34
S22	9	Huss.in. near2 rolf. in.	US-PGPUB; USPAT	OR	ON	2008/03/26 10:15
S23	291	worm near2 gear near5 magnet\$5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/09/18 11:56
S24	939	pump.clm. and (distributor valve). clm. and rotat\$3. clm. and thread\$2. clm.	US-PGPUB; USPAT	OR	ON	2008/09/19 09:29
S25	367	pump.clm. and (distributor valve). clm. and (rotat\$3. clm. with thread \$2.clm.)	US-PGPUB; USPAT	OR	ON	2008/09/19 09:29

S26	160	(417/442).OCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 08:18
\$27	602	(417/494).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 08:26
\$28	209	S27 and (thread \$3 screw\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/09/24 08:26
S29	361	(417/502).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 08:41
S30	109	S29 and (thread \$3 screw\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/09/24 08:42
S31	826	(74/127).OCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 08:51
S32	1362	(74/409).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/09/24 09:15
S33	580	S32 and (thread \$3 screw\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/09/24 09:17

9/ 24/ 2008 9:33:17 AM C:\ Documents and Settings\ pstimpert\ My Documents\ EAST\ Workspaces\ 10722165. wsp